

# SPEED MATRIX

\*All turns are full turns. USE PT-1 tension gauge.

<b>KNOTS</b>	<b>0-7</b>	<b>BASE RANGE 7-14</b>	<b>12-18</b>	<b>15-20</b>	<b>18-25</b>
<b>FORESTAY</b>	BASE	26-3/8"	BASE	BASE	BASE
<b>UPPERS</b>	-1	38	+1	+2	+3
<b>LOWERS</b>	-2	21	+1	+2	+3
<b>DIAMONDS</b>	-1	23.5	+1	+2	+3
<b>BOARDS</b>	-1—AP	Pin @ AP	AP—+1	+1—+2	+2—+3

## CALIPERS @ BASE

	<b>PORT</b>	<b>STARBOARD</b>
<b>UPPERS</b>		
<b>LOWERS</b>		
<b>DIAMONDS</b>		
<b>FORESTAY</b>		