

J/22: LOOS MODEL A RIG SETTINGS



TWS	UPPERS	TURNS	LOWERS	TURNS	HEADSTAY NUMBER
0 to 4	23	+ 1	20	+ 1/2	4
5 to 9	30	+ 1	24	+ 1/2	6
10 to 13	35	+ 1	27	+ 1/2	9
14 to 16	39	+ 1	32	+ 1/2	15
17 to 18	41	+ 1	35	+ 1/2	19
18 to 25	44	+ 1	42	+ 1	23