

J/22: LOOS MODEL PT1 RIG SETTINGS



TWS	UPPERS	TURNS	LOWERS	TURNS	HEADSTAY NUMBER
0 to 4	15	+ 1	11	+ 1/2	3
5 to 9	20	+ 1	15	+ 1/2	5
10 to 13	25	+ 1	19	+ 1/2	8
14 to 16	28	+ 1	21	+ 1/2	10
17 to 18	31	+ 1	25	+ 1/2	13
18 to 25	33	+ 1	30	+ 1	17