



QUANTUM *Melges 24* **Quick Tune**

**This Guide is for the RONSTAN turnbuckles on the White Mast*

TWS	UPPERS	LOWERS	MAST SAG	JIB LEAD	SPIN
0 - 4	- 6	- 4	1" +	0	R1
5 - 6	- 4	- 2	1"	0 or 1	R1
6 - 8	- 2	- 1	3/4" to 1"	1	R2
8 - 10	BASE	BASE	3/4"	2 <i>(3rd Screwhead)</i>	R2
10 - 12	+ 3	+ 2	3/4" to 1/2"	2	R2
13 - 15	+ 6	+ 4	1/2"	2	R2
16 - 18	+ 9	+ 6	1/2" to 0	2 or 3	R2
18 - 20	+ 12	+ 8	0	3	R2
20 - 23	+ 15	+ 10	0 to poke	4	R1 or R2
24 - 26	+ 19	+ 15	0 to poke	5 or 6	R1
26 +	+ 22	+ 21	0 to poke	6 or 7	R1

All Turns Are From BASE SETTING

Rake = 36' 7"

16 on LOOS B Tension Gauge

14 on the PT-2 LOOS Tension Gauge